


**NEW**

Gasket set, electric motor | Dichtungssatz, Elektromotor | Kit de joints, moteur électrique | Kit de juntas, motor eléctrico | Kit guarnizioni, motore elettrico | Zestaw uszczelek, silnik elektryczny | Kit de vedação, motor elétrico | Afdichtingsset, elektromotor

**VOLVO**



**186.340**



TecDoc

<b>S60</b>			
T8 Plug-in Hybrid AWD (ASIA)	B4204T34   ERAD2	32240718	2019 ->
<b>S60 III (224)</b>			
T8 Drive-E AWD	B 4204 T28		
T8 Hybrid Polestar AWD	B 4204 T39	32240718	2019 ->
T8 Twin Engine Polestar AWD	B 4204 T48   B 4204 T53		
T8 Plug-in Hybrid AWD	B 4204 T27   B 4204 T35		
T8 Twin Engine AWD	B 4204 T34	32240718	2019 -> 2022
T6 Twin Engine AWD	B 4204 T34   B 4204 T46		
T8 Hybrid Polestar AWD	B 4204 T48		
T8 R-Design Hybrid AWD	B 4204 T35	32240718	2020 ->
<b>S90</b>			
T8 Plug-in-Hybrid AWD	B4204T35   ERAD2	32240718	2018 ->
T8 Plug-in-Hybrid AWD	B4204T34   ERAD2	32240718	2020 ->
<b>S90 II (234)</b>			
T8 Plug-in Hybrid Polestar AWD	B 4204 T35	32240718	2017 -> 2022
T8 Plug-in Hybrid AWD			
T8 Hybrid AWD	B 4204 T28	32240718	2018 ->
T8 Hybrid AWD	B 4204 T34	32240718	2018 -> 2022
T8 Hybrid Polestar AWD	B 4204 T34   B 4204 T53	32240718	2019 ->

**ElringKlinger AG | Aftermarket Division**

Max-Eyth-Straße 2 | D-72581 Dettingen/Erms

Fon +49 7123 724-799 | Fax +49 7123 724-798

service@elring.de | www.elring.com

V51.12/2024



**Das Original**

**NEW**

Gasket set, electric motor | Dichtungssatz, Elektromotor | Kit de joints, moteur électrique | Kit de juntas, motor eléctrico | Kit guarnizioni, motore elettrico | Zestaw uszczelek, silnik elektryczny | Kit de vedação, motor elétrico | Afdichtingsset, elektromotor

**VOLVO**



**V60 III (225)**

T8 Plug-in Hybrid AWD B 4204 T34 32240718 2018 -> 2022

T8 Plug-in Hybrid Polestar AWD  
T8 Hybrid Polestar AWD B 4204 T35 32240718 2019 ->

T6 Plug-in Hybrid AWD  
T8 Plug-in Hybrid Polestar AWD B 4204 T46 32240718 2019 -> 2022

**V90 II Kombi (235)**

T8 Plug-in Hybrid Polestar  
T8 Plug-in-Hybrid AWD AWD B 4204 T35 32240718 2016 -> 2018

T8 Plug-in Hybrid Polestar AWD  
T8 Hybrid AWD B 4204 T34 32240718 2018 -> 2022

T6 Plug-in-Hybrid AWD B 4204 T46 32240718 2020 -> 2022

**XC60 II**

T8 Plug-in Hybrid AWD B4204T35 | ERAD2 32240718 2018 ->  
T8 Plug-in Hybrid AWD B4204T34 | ERAD2 2020 ->

**XC60 II (246)**

T8 Hybrid AWD B 4204 T28 | B 4204 T57 |  
B 4204 T35 32240718 2017 -> 2022

T8 Hybrid AWD B 4204 T34 32240718 2018 -> 2022  
T8 Drive-E AWD B 4204 T28 2019 ->

T8 Hybrid Polestar AWD B 4204 T34 | B 4204 T48 32240718 2019 -> 2022  
T8 Hybrid Polestar AWD B 4204 T39 2020 ->

T6 Plug-in Hybrid AWD B 4204 T45 | B 4204 T46 32240718 2021 ->

B4 Plug-In Hybrid B 4204 T46 32240718 2021 -> 2022  
B4 Plug-In Hybrid AWD B 4204 T46

**XC90 II (256)**

T8 Hybrid AWD B 4204 T28 | B 4204 T35 |  
B1APHEV 2015 -> 2018

T8 Plug-in Hybrid Polestar AWD B 4204 T35 2015 -> 2022  
T8 Hybrid AWD

T8 Hybrid Polestar AWD B 4204 T34 2019 -> 2022  
T8 Twin Engine AWD

T8 Hybrid Polestar AWD B 4204 T35 | B 4204 T39 2020 -> 2022

**EkringKlinger AG | Aftermarket Division**

Max-Eyth-Straße 2 | D-72581 Dettingen/Erms

Fon +49 7123 724-799 | Fax +49 7123 724-798

service@elring.de | www.elring.com

V51.12/2024



**Das Original**